


Note: Corners should have been Plotted West so that Montgomery Co. cor would fall where Wilson Co. cor is now plotted, and Wilson Co. cor should be plotted west of where it is now plotted.



NW. Cor. 16-31-15
31.5' N. to 1 1/2" pipe
34.2' S.E. to Hdge. Cor. Post.